



S2000 Lubrication Procedure

You must put in high temperature UREA grease or equivalent into groove of your release bearing.

The release bearing guide and clutch fork also need to be lubricated with UREA grease.

Failure to follow installation procedures will VOID any warranty provided with this clutch kit.

